
IMx-M USB drivers installation

Please perform the following steps in order to install USB drivers:

1. Uninstall the previous USB drivers installation by opening

   "CDMUninstaller_vl.4/CDMuninstallerGUI.exe"



   - Vendor ID is 0403 and Product ID is 6001.
   - Press Add.
   - Select the driver listed.
   - Press Remove Devices.
   - Close CDM Uninstaller window.

2. Go back to the "USB drivers" folder and run "**CDM v2.12.00 WHQL Certified.exe**".
3. When connecting a CMM or PRM board for the first time, wait 2 minutes until the driver recognizes the device and assigns an available COM port number to the device.

   This COM port number will then be selectable in "IMx-M Manager" software.

SKF Condition Monitoring Center - Luleå
Aurorum 30, S-977 75 • Luleå, Sweden
Tel +46 (0)31 337 10 00 • Fax +46 (0)920 134 40